

SSanYong Rexton 2.7 Xdi 2006

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

