

Mitsubishi Outlander 2.2 DI-D 156HP

1. Box type: VT101204.
2. Find plugs for rail pressure sensor. Disconnect it and connect box adapter between.

