

## Hyundai Santa Fe 2.2CRDi 150HP 2007

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

