

## Citroen Jumper 2.2HDi 102HP 2005

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

