

BMW 530d 218HP 2003

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

