

New Holland T8030

1. Box Type: VT101201



2. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

