

Saab 9-5 1.9TiD 150HP 2007

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

