

Honda Accord/CR-V 2.2 i-DTEC 150HP

1. Box type: VT301200-003.
2. Find plugs for rail pressure sensor and manifold absolute pressure. Disconnect it and connect box adapter between.

