

Ford Focus 1.8TDCi 115HP 2006

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

